

Fig. 1




Fig. 1c

FIG. 1a




Fig 1a





Fig-1b






Fig-1






Fig-2a



A hand-drawn schematic diagram of a mechanical assembly. The diagram shows a rectangular frame with a wavy line on the left side. A horizontal bar, labeled 33, is positioned at the top. An arrow labeled 40 points upwards from the center of the frame. On the right side, there is a vertical assembly. A component labeled 144 is at the top right corner. Below it, a vertical rod is shown with a component labeled 120. A bracket labeled 121 spans a section of the rod. A component labeled 122 is located on the rod. A line labeled 121 points to a small square component at the bottom of the rod. A line labeled 122 points to a small square component on the rod. A line labeled 120 points to the rod itself. A line labeled 144 points to the top right corner. A line labeled 52 points to the right side of the frame. A line labeled 72a points to a small square component at the top right corner. A line labeled 72b points to a small square component on the rod.

Fig-5




Fig-6

10021470-103001

Fig-7





Fig-8 54